

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
1	Acronyms:		NSF, Navajo Superfund				USEPA, United States Environmental Protection Agency					BIA, Bureau of Indian Affairs NTUA, Navajo Tribal Utility Authority						
2			NMED, New Mexico Environment Department				NHA, Navaj Housing Authority					PAH, Polyaromatic Hydrocarbc OSMRE, Office of Surface Mining Reclamation and Enforcement						
3			N, S, E, W, The cardinal directions				Hwy, Highway					RBC, risk based concentration						
4			EPA, Environmental Protection Agency				Rte, Route					FOSC, Federal On Scene Coordinator						
5			NNEPA, Navajo Nation Environmental Protection Agency				PRP, Potentially Responsible Party					I-40, Interstate 40						
6	For information regarding any of these sites please contact Pam Maples, Navajo EPA Superfund at 928-871-7187 ~ pamaples@navajo-nsn.gov																	
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
8	SDV001	Alamo SDV	NND986675197	This SDV was not in the original database of dip vats but has been added bcause in is in the NSF spreadsheet.			This SDV may hnot exist.			Needs investigation					01/29/13	Restricted		Land Use Restriction on Public Record.
9	SDV002	Alamo Springs SDV	2013	The SDV is located approximately 0.5 mile E of US Hwy 169 between mile posts 27 and 26 on a paved road that passes by the baseball fields at Alamo.	34.395055	-107.48278	Phase 1 assessment complete. Samples were all non-detect. Samples did not exceed screening criteria (40 ppm tosaphene). Closure document O.A.Systems	2002	No Further Action		2002		Alamo Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
10	SDV003	Alfred Taylor SDV (Chinle West)		The SDV is located W of Chinle, apprcimately 10 miles W of US Hwy 191 and N of Navajo Rte N-8090, in a very remote area.	36.20401	-109.727277	Phase 1 assessment complete. Samples were all non-detect. Samples did not exceed screening criteria (40 ppm tosaphene). Closure document O.A.Systems	2002	No Further Action		2002		Chinle Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
11	SDV004	Aneth SDV		2500 ft SE of Chapter House	37.213483	-109.181717				Needs investigation								
12	SDV005	Arrowhead SDV		Approx. 6.5 miles E of Dilkon; 1000 ft N of BIA Rte N-15; 8 miles W of the intesection of Rt-5/Hwy 77 at Indian Wells.	35.382441	-110.008519	Bioremediation; Oversight by NSF; BIA, as PRP. Capped with local virgin soil. Last sample analyzed 11/23/04. Closure report ASCG.	2004	No Further Action		2005	PO Box 3049 Indian Wells, AZ 86031-3049	Indian Wells Chapter	1 mile NW of BIA rte N-15 and N-6 junction, Indian Wells, AZ	01/05/06	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
13	SDV006	Arthur Lee SDV			35.34986667	-110.5010833	Phase I and Phase II. Sample results 11-12-2002: Chlordane, Heptachlor, Heptachlore epoxide, and Toxaphene all sampled. Toxaphene remains above the standard in many samples.	2002		Needs remediation		Elephant Butte, AZ USGS Quad			04/28/20			
14	SDV007	Baca #1 (Old) SDV	NND986669638	6 miles south of chapter 100 ft north of well 16K-317 Baca #1 Vat can be found by traveling south of interstate 40 on state hwy 412 for 1/4 mile, turning west on an improved dirt road for approx 3 miles. Adjacent to windmill 1 16T -317.	35.37055	-108.087742	Toxaphene in soil is higher than the standard. No date on the sample info.	2002		Pending further assessment		Prewitt USGS Quad			04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
15	SDV008	Baca (New) SDV		6 miles south of chapter 1/2 mile east of well 16K-317	35.3711	-108.08469	IT is unclear in all of the reports if Baca #1 , #2,and/or Haystack are all the same site. However, there are two that are visible from I-40. Haystack has an entry in this database with different coordinates.	2002		Pending further assessment					04/28/20			
16	SDV009	Bass Lake SDV	NND986669182	7 SW CC Vat is located 5.4 miles southeast of Coyote Canyon, NM, approx 3.1 miles west of Indian Service, route 9	35.718424	-108.686004	Toxaphene is above the standard slightly is some samples. No dates easily discovered.	2002		Pending further assessment			Coyote Canyon Chapter		04/28/20			
17	SDV010	Becenti Chapter House SDV		9 miles N of Crownpoint; 0.5 miles W of Hwy 371 and 200 yds S from the Chapter house.	35.812732	-108.164635	Bioremediation; Oversight by NSF; BIA, as PRP with ASCG as subcontractor; Capped with local virgin soil. Last sample analysed 10/01/04. Closure report ASCG.	2004	No Further Action		2005	PO Bpx 708 Crownpoint, NM 87313-0708	Becenti Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
18	SDV011	Becalabito #1 SDV	NND986669141	.5 mile west of Beclabito, NM Trading Post? Beclabito #2 is located northwest of Beclabito Trading Post. Travel north of state hwy 504 on Tribal Road # 5027 for 0.6 miles	36.842508	-109.021214	Toxaphene is above the standard slightly is some samples. No dates easily discovered. Probably 1998.	1998		Pending further assessment			Beclabito Chapter		04/28/20			
19	SDV012	Becalabito School #2 SDV		Beclabito #2 is located northwest of Beclabito Trading Post. Travel north of state hwy 504 on Tribal Road # 5027 for 0.6 miles	36.840545	-109.015067	Toxaphene is above the standard slightly is some samples. No dates easily discovered. Probably 1998.	1998		Pending further assessment			Beclabito Chapter		04/28/20			
20	SDV013	Beshbito-Jeddito SDV		2 miles N of Hwy 264, adjacent to Cedar Public School, Jeddito T28N;R23E Binder 9 says: Keams Canyon approx 1.5 miles west of Steamboat alongside state highway 264. Binder 4 & File Folder Gallup-1 say 1.5 miles west of Steamboat, AZ 500 yds SW of well 7T-543	35.769325	-109.979849	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. [Bioremediationcell?] Sampled and analyzed on 12/94. Sampled in 1998 and it was still high.	1998		Pending further assessment		PO Box 798 Keems Canyon, AZ 86034	Jeddito Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
21	SDV014	Birdsprings #1 (5-2-1) SDV		The SDV is in a remote area approximately 0.75 mile S of Navajo Rte N-15 near the old chapter house.	35.297507	-110.803755	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm toxaphene). There are 3 sites in this area. The lab data does not specify to which site these results belong.	2002		Pending further assessment			Birdsprings Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)	
7																			
22	SDV015	Birdsprings #2 (5-2-2) SDV		The SDV is located SE of Leupp, AZ and NW of Winslow, AZ It is located on the Dick residence, which is 0.2 mile NW of windmill 5K-319, and approximately 1.2 miles S of BIA Route 2, near Bird Springs, AZ.	35.184023	-110.823088	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). There are 3 sites in this area. The lab data does not specify for sure that they go with this site but there is a good possibility that they do. No closure report	2005	No Further Action		None		Birdsprings Chapter		04/28/20				
23	SDV016	Birdsprings #3 (5-2-3) SDV			35.282982	-110.957982	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). There are 3 sites in this area. The lab data does not specify to which site these results belong.	2002		Pending further assessment			Birdsprings Chapter		04/28/20				
24	SDV017	Black Mountain SDV	NND986669133	The SDV is locatdc on BIA 145, off State Rd 53, approximately 12 miles S of Mountain View community. Black Mountain is 1 mile E of the SDV.	34.898625	-108.298104	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). No closure document but toxiphene was below 2.0 ppm in all smaples as of 2002.	2002	No Further Action	Find the closure report	None		Ramah Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.	
25	SDV018	Black Rock Butte SDV		3 N BRB 1/2 mile northeast of well 11T-505 which is 3 miles north of Black Rock Butte. There is another called Tse Zhin Shi Gaah-Black Butte in the file. The picture has similar landscape. Perhaps there were 2 SDVs here.	36.187463	-109.289265	Phase II lab results 11-13-2002 show toxaphene high in one sample.	2002		Pending further assessment					04/28/20				
26	SDV019	Black (Water) Springs SDV	NND986669653	1.5 E Well # 14-5-6 ? Or 9 miles west of Nachitti, NM. West on state hwy 134 from Sheep Springs, NM approx 9.5 miles to Indian Service rd 30 turnoff.	36.029683	-108.831122	Toxaphene is above the standard slightly is some samples.	1998		Pending further assessment					04/28/20				
27	SDV020	Blue Canyon Road Cell #1 SDV		Adjacent to the SDV?	0	0	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical fesults. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/02/94. The sample data is for this cell #1 not the SDV area.	1994	No Further Action	Find the closure report	None	PO Box 366 Ft. Defiance, AZ 86504	Fort Defiance Chapter		04/28/20				

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
31	SDV024	Burnham SDV		The SDV is located just N of Navajo Rte N-5 near the Burnham Chapter House, just behind the hill with "Burnham" spelled out on rock.	36.364876	-108.500729	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Burnham Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
32	SDV025	Burnt Corn SDV		The SDV is remotely located with respect to paved roads. However, it is near an apparent grow9ing community on a maintained dirt road	36.157115	-110.066987	Phase 1 assessment complete. Samples were just below but did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Piñon, Blue Gap, and whipporwill Chapters		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
33	SDV026	Cameron #1 (3-4-1) SDV		One of these 2 sites is aprox. 1 mile off hwy 89 west of chapter house. Same as SDV128.	35.781809	-111.522175	No lab data on file.			Needs investigation					04/28/20			
34	SDV027	Cameron #2 (3-4-2) SDV		The SDV is located off of US Hwy 89 and State Hwt 64 with a small residential community area.	35.871049	-111.427117	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Cameron Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
35	SDV028	Carrizo Mountain SDV			36.803292	-109.186771	As of 10/2002 toxiphene was present at levels above the action levels			Needs remediation					04/28/20			
36	SDV029	Casmero Lake SDV	NND986667814	5 miles south of Borrego Pass, NM or 100 ft southwest of Chapter House, 3000 ft east of NTUA system well 16T-588. There has been a road built on top of half of this SDV. Only the entrance pad is visible.	35.504443	-108.030381	No lab data on file.			Needs investigation					04/28/20			
37	SDV030	Cherry Town SDV		100 yards W of Hwy-169; 200 yards N of NHA subdivision; There's a housing addition, 100 yards SE of the dip vat.	34.367923	-107.496355	Bioremediation; Oversight by NSF; BIA, as PRP with ASCG as subcontractor; Capped with local virgin soil. Last sample analyzed 09/27/04. Closure report ASCG.	2004	No Further Action		2005	PO Box 827 Magdalena, NM 87825-0827	Alamo Chapter		01/05/06	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
38	SDV031	Chilchinbeto #1 (8-2-1) SDV		One of these 3-5 sites is 1/2 mile southeast of trading post.	36.522217	-110.064733	Questionnaires were sent out to the chapter by the Navajo Nation EPA and the Navajo Superfund Office. The response to one indicated that there were five vats, while the other reported six. If any of these sites have been sampled, the results are not available.			Needs investigation					04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
7																		
42	SDV035	Coalmine Canyon #1 (3-1-1) SDV		One of these 2 sites is 6 miles south of hwy 264, about 100 ft east of windmill 3M-175. NSF notes. The original coordinates plot on top of a rock formation. latitude was probably calculated incorrectly. Driving directions plot to the current placemark. Compare with waterwell data.	36.909097	-111.152952	No files in the database			Needs investigation					04/28/20			
43	SDV036	Coalmine Canyon #2 (3-1-2) SDV		One of these 2 sites is 6 miles south of hwy 264, about 100 ft east of windmill 3M-175.	36.045345	-110.865414	No files in the database			Needs investigation					04/28/20			
44	SDV037	Coppermine (1-3-1) SDV	NND983479247	5 N CH, or Navajo Route 10 or 500 ft west of windmill 1A-115 off dirt road.	36.394934	-111.419265	No files in the database			Needs investigation					04/28/20			
45	SDV038	Cornfields SDV		8 miles SW of Hwy-264/191 intersection, 2miles E of BIA Rte-15, 300 ft SE of the Chapter House. 1/2 S CH or Near well 17-M-91A, southwest of Cornfields 1/5 mile. In a field near year-round residences and the Cornfields Chapter House. There is a church opposite the site. A windmill and well are 100 yds downgradient from the vat.	35.648448	-109.681932	Removal; Oversight by NSF; BIA, as PRP. Capped w/ Imported fill material (from Waste Management had PAHs < EPA Region 3's RBC soil levels); Closure dreport EMI	2003	No Further Action		2003	PO Box 478 Ganado, AZ 86505-0478	Cornfields Chapter	8 mi S on N15 Ganado, AZ 86505-0478	04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
46	SDV039	Cottonwood SDV		Rte 4 Chapter House Rd. Cottonwood. T31N;R23E approx 0.25 miles north of Navajo Route 4 at Cottonwood ? 10 W SS CH ? Or 300 ft north of wells 10R-51A and 10R-51B which are 1/4 mile north of Cottonwood School.	35.986908	-109.745984	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical fesults. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/94. These are notes from NSF.			Check these against SDV040		PO Box 1139 Chinle, AZ 86503	Tslani Chapter (Cottonwood Chapter)			Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
47	SDV040	Cottonwood New SDV		approx 0.25 miles north of Navajo Route 4 at Cottonwood ? 10 W SS CH ? Or 300 ft north of wells 10R-51A and 10R-51B which are 1/4 mile north of Cottonwood School. There is a feature that looks like a disposal pit 120 ft SE of the SDV.	36.077026	-109.887573	As of 2002, one of the two dip vats at Cottonwood had toxaphene above the action level. All documents in the database just say Cottonwood.			Check these against SDV039					04/28/20			
48	SDV041	Counselor SDV		Binder 5 says no vat at Counselor. File Folder 6 says: there are two vast at counselor. One is on private land and the other is burried by arroyo wash out over the years (since 2006) . It is supposedly located at least 10 miles south of Lybrook, NM.	placemark 10 Mi S of Lybrook	0				Find this SDV					04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
7																		
55	SDV048	Denehotso #1 (8-3-2) SDV		One of these sites is located 1 1/4 miles west of Denehotso Chapter House. The site is .1 mile south of hwy 160 at mile marker 416. (Alternate Coordinates: 36, 49.867' latitude 109, 51.717' longitude) Vat may be buried	36.818319	-109.875293	This site appears to have been remediated in the 1990's.	1996	No Further Action	Find the closure report	None				04/28/20			
56	SDV049	Denehotso #3 SDV		There was a SDV "behind the school". It may have been remediated.	36.848035	-109.846999	The SDV location may be indicated by concrete pad behind some trees half way between the NW corner of the school building and the SE corner of the dry (western) sewer lagoon.			Needs investigation					04/28/20			
57	SDV050	Dog Springs SDV		Located at windmill IK-221, 4 miles south of Page highway. Vat is Buried in sand.	35.372957	-110.089848	As of 2002 there was still taxaphene above the action levels. The 2003 samples were all non-detect.	2003		Pending further assessment					04/28/20			
58	SDV051	Escandito Dixon SDV		1.3 miles S of BIA Rte N-15 across Coyote Wash on Hollow Rock Rd.	35.348728	-110.361868	Bioremediation; Oversight by NSF; BIA, as PRP. Capped with local virgin soil. Closure report: EMI	2004	No Further Action		2005	HCR 63 Box E Winslow, AZ 86031	Dilkon Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
59	SDV052	Fluted Rock SDV		The SDV is marked " corrals" on the Sawmill USGS 7.5 minute topographic map. It is located 4,000 feet NW of Fluted Rock Lake.	35.946848	-109.240098	As of 1996, toxaphene seems to be below the action level.	1996		Find the closure report					04/28/20			
60	SDV053	Forest Lake #2 SDV		The SDV is located on Navajo Rte N-4 approximately 13 miles N of the Forest Lake Chapter house, S of the entrance to the Peabody Black Mesa Mine. This SDV was not in the original database of dip vats but has been added.	36.401353	-110.38709	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm toxaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Forest Lake Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
61	SDV054	Ganado SDV		The questionnaire reveals two dip vat sites at Ganado. The report says that they are about one mile northeast of the chapter house. One of them (called #2) was sampled. Binder 4 says that there are 3 sites in Ganado Chapter. This is not supported by interviews with locals. During field reconnaissance, after talking with locals to obtain directions, ASCG staff found the likely rubble of one dip vat that was pushed over into an adjacent ravine.	35.718006	-109.529604	In 1998, toxaphene was less than the standard at one of the dip vats. Probably #2. See SDV165.			Needs investigation					04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
69	SDV062	Houck North SDV		The SDV is located 3 miles NW of the Chpater Housenear windmill marked on the HOUK USGS 7.5 minute topographic map. There is only one site sketch in the file.	35.299783	-109.21888	As of 1995 toxaphene was above the action levels.	1994		Pending further assessment					04/28/20			
70	SDV063	Houck South (Old Hogan) SDV		The SDV is located west of St. Anselm Catholic Church inside a private gate north of the private driveway. The site is 100 NW and downhill of an old abandoned stone hogan.	35.278623	-109.225368	This SDV has not been sampled. It has an open 30 foot deep, ten foot by ten foot dry well. There are residences with children close by.			Needs investigation. NEEDS the disposal pit backfilled!!!					04/28/20			
71	SDV064	Huerfano SDV		The SDV is located approximately 100 yards from a dirt road. Several houses and the Chapter House are located within approximately 200 yards. The Chapter house is located S of NM Rd 44.	36.453893	-108.003651	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Huerfano Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
72	SDV065	Inscription House (2-2-1) SDV		The SDV is on a heavily trafficked dirt road less than a mile from Navajo Rte N-16, The Inscription House Chapter house, and a community store.	36.642434	-110.755879	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Inscription House Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
73	SDV066	Jeddito Island SDV	NN0 000 125 575	2 miles N of Hwy 264, adjacent to Cedar Public School, Jeddito. T28N;R21E. Binder 9 says: Keams Canyon Approx 0.25 mile north of state highway 264 in Jeddito. Binder 4 says 200 ft SE of Jeddito Chapter Wharehouse	35.776958	-110.131926	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/94.	1994	No Further Action	Find the closure report	None	PO Box 798 Keems Canyon, AZ 86034	Jeddito Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
74	SDV067	Jeddito Windmill SDV		Associated with windmill 07 T 525. These coordinates seem to plot to a SDVin Jeddito.	35.776497	-110.133397	Has not been found yet.			Find this SDV, windmill 07 T 525				04/28/20				
75	SDV068	Kaibeto #1 (1-2-1) SDV	NND983478694		36.610537	-111.076449				Needs investigation				04/28/20				
76	SDV069	Kaibeto #2 (1-2-2) SDV		The SDV is less than 1 mile N of the Chapter House.	36.597419	-111.06912				Needs investigation				04/28/20				
77	SDV070	Kaibeto #3 (1-2-3) SDV		Turn West at milepost 320, and take the middle fork. The vat is then 7.5 miles (6 miles from RR tracks). Go west out to White Rock Hills, then left and South around the hills and on to the windmill. Stay on the main road.	36.570563	-111.220656				Needs investigation				04/28/20				
78	SDV071	Kayenta #1 Cut Foot Wash (8-1-1) SDV		The Chapter questionnaire says that there were five sites but three of them have been dismantled or no longer exist.	36.683187	-110.237458	Going to have to sort this out. Which sampling goes with which Kayenta SDV.			Needs investigation				04/28/20				

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
79	SDV072	Kayenta #2 Sand Springs (8-1-2) SDV		The Chapter questionnaire says that there were five sites but three of them have been dismantled or no longer exist.	36.732371	-110.323881	Going to have to sort this out. Which sampling goes with which Kayenta SDV.			Needs investigation					04/28/20			
80	SDV073	Kayenta #3 Forest Lake #2 (8-1-3) SDV		The Chapter questionnaire says that there were five sites but three of them have been dismantled or no longer exist.	36.730239	-110.262868	Going to have to sort this out. Which sampling goes with which Kayenta SDV.			Needs investigation					04/28/20			
81	SDV074	Kayenta #4 (8-1-4) SDV		were five sites but three of them have been dismantled or no longer exist. NSF notes.	36.401363	-110.38702	Going to have to sort this out. Which sampling goes with which Kayenta SDV.			Needs investigation					04/28/20			
82	SDV075	Kayenta #5 (8-1-5) SDV		The Chapter questionnaire says that there were five sites but three of them have been dismantled or no longer exist.	36.363693	-110.347819	Going to have to sort this out. Which sampling goes with which Kayenta SDV.			Needs investigation					04/28/20			
83	SDV076	Kinlecheeny, James SDV		During field exploration, all roads leading to the location of well 8A-277 were either washed out or otherwise impassable. Still unknown.	0	0				Find this SDV, windmill 8A-277					04/28/20			
84	SDV077	Kinlichee SDV		3 NE CH (NW of school)	35.754451	-109.432318	USEPA Region IX NN SDV project 1998 listed sample results varrying from lows to highs (like >20 <100) for each sample.	1998		Pending further assessment					04/28/20			
85	SDV078	Kitsilli (Black Mesa) SDV		1 SW BM S = School? 200 ft west of well # 4K-382 which is 1/4 mile west of Kitsilli preschool.	36.343442	-110.062498	As of 2002 toxaphene was below the action level, but just below.	2002		Pending further assessment					04/28/20			
86	SDV079	Lake Valley SDV	NND 986 669 158	28 miles north of Crownpoint on state hwy 371, 100 ft west of chapter, 60 ft south NTUA or Travel north of Crownpoint 20 miles on hwy 371 then turn northeast on Navajo 7059 and go 9 miles.	36.0475	-108.147577	This SDV was sampled in 1995. Some samples were below the action level.	1995		Pending further assessment					04/28/20			
87	SDV080	Largo #1-T SDV		T14N;R13W Approx 2 miles north of US interstate 40 and along state highway 57 in Thoreau.	35.415473	-108.173712	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical fesults. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/06/94. Other than the remedial cell information, the lab results don't differentiate between the two sites.	1994		Pending further assessment					01/22/10	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
88	SDV081	Largo T #2 SDV		No such SDV? Ha! Found it.	35.415799	-108.17373	No files in the database			Needs investigation					01/22/10	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
7																		
96	SDV089	Los Noris SDV		Thre SDV is located on BIA 153, S of Mountain View community off BIA 125. The site is in a scrubbybrush field	34.817287	-108.529388	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Ramah Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
97	SDV090	Lupton #1 SDV		The SDV is located 5.5 miles W of Lupton Chapter House, on I-40 approximately 1.5 miles N of I-40.	35.310963	-109.114745	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Lupton Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
98	SDV091	Lupton #2 SDV		Approx 5 miles west of Lupton, AZ and 1 mile south of US interstate 40. Vat is missing trench, could be partially remediated. NSF notes. Or they missed it. There is a concrete structure and a possible disposal pit 88 ft ENE of these corrals.	35.302503	-109.098743	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Needs investigation Find the closure report			Lupton Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
99	SDV092	Lupton Cell #1 SDV		I-40, exit 367. On Rte 12 Lupton, AZ.	35.34026	-109.072619	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical fesults. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/05/94.	1994	No Further Action	Find the closure report		PO Box 403 Lupton, AZ 86508	Lupton Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
100	SDV093	Many Farms SDV		1/4 mi north of well 10R-98 which is 1/4 mile east of Many Farms	36.351788	-109.612953		1995		Pending further assessment				04/28/20				
101	SDV094	Mariano Lake SDV		1.2 miles N of BIA Rte N-49	35.59124	-108.307805	Bioremediation; Oversight by NSF; BIA, as PRP with OA Systems as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Last sample analyzed 08/15/05. These are NSF notes. 2002 toxaphene was above the actin levels.	2002		Pending further assessment		PO Box 520 gallup, NM 87305	Mariano Lake Chapter		12/03/05	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
102	SDV095	Mexican Springs (Chuska) SDV		In the Chuska Mountains. W off of Hwy 491 on BIA Rte N-30 beyond Nakaibeto within the Squirrel Springs Picnic Grounds 12 miles up a rugged road.	35.904649	-108.89525	Removal; Oversight by NSF; BIA, as PRP. Capped with local virgin soil. Closure Report: EMI	2003	No Further Action		2005	PO Box 93 Mexican Springs, NM 87320	Mexican Springs Chapter		01/18/05	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
103	SDV096	Mexican Water SDV		The SDV is located approximately 2 miles N of US Hwy 160 at mile post 433.	36.962733	-109.643028	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm tosaephene). Closure document pending.	2002	No Further Action	Find the closure report	None		MexicanWater Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
104	SDV097	Mountain Sheep Overpass		May be renamed Roof Butte SDV. The Roof Butte SDV coordinates plot over close to Round Rock. Sanostee Big Valley coordinates plott here as well.	36.421875	-109.102022				Needs investigation								
105	SDV098	Mulholland SDV		3.4 miles N of BIA Rte N-9 adjacent to the S side of the Smith and Becenti ranch.	35.791291	-108.266382	Bioremediation; Oversight by NSF; BIA, as PRP with OA Systems as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Last sample analyzed 08/15/05. These are NSF notes. As of 2002 toxaphene was present above the action levels. Site has been remediated. Locals said there was a chain link fence up around an earthen dam area. This is now gone, with only wood and metal debris remaining.	2002	No Further Action	Find the closure report	None	PO Box 708 Crownpoint, NM 87313-0708	Becenti Chapter		12/29/05	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
106	SDV099	Na Ah Tee SDV		4 miles W of Hwy 77, 0.65 miles S of MP-23 with access from an unpaved road. Approximately 9 miles S of Whitecone. 500 ft south of existing fence line, vat is burried.	35.487502	-110.141987	Removal; Oversight by NSF; BIA, as PRP with ASCG as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Last sample analyaed 11/29/04.	2004	No Further Action		2005	PO Box 3338 Indian Wells, AZ 86031-3338	Whitecone Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
7																		
107	SDV100	Nageezi SDV		The SDV is located approximately 10.5 miles W of US Hwy 550 at mile post 116. It is close to several businesses	36.18244	-107.839547	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Nageezi Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
108	SDV101	Naschitti SW SDV		Sweetwater Area, no vat evident in the 2006 field investigation. or 1/2 mile east of well 14-5-6, which is 12 miles west of Chapter House. NSF notes. These directions make no sense. Sweetwater is over 70 miles from Naschitti. There is what looks like a SDV 120 yards south of SDV102.	36.098682	-108.65706	The lab data doesnot specify which of the two SDVs the rtesults are for.			Find this SDV well number 14-5-6					04/28/20			
109	SDV102	Naschitti E SDV		1.5 East of Well # 14-5-6	36.099687	-108.65691	The lab data doesnot specify which of the two SDVs the rtesults are for. Probably this one.	1995		Pending further assessment					04/28/20			
110	SDV103	Navajo Mountain #1 (2-1-1) SDV	NND983478702	5 S CH The SDV is in AZ. It is 63 yarde WSW of a well and tank. Extant.	36.944405	-110.791978	As of 1996 the toxaphene appears to be below action level at one of these two sites. The lab data doesnot specify which of the two SDVs the rtesults are for.			Needs investigation					04/28/20			
111	SDV104	Navajo Mountain #2 (2-1-2) SDV		The SDV is located approximately 0.3 mile W of BIA Rte N-16 in Navajo Maountin, UT. It is just north of the new chapter house.	37.016435	-110.795157	Toxaphene was below the action levels in 2006. No closure document on file.	2006	No Further Action	Find the closure report	None				04/28/20			
112	SDV105	Nazlini SDV	NND983469578	14 miles northeast of Ganado on Navajo Route 27.	35.901236	-109.442391	Phase II report indicates that this is a remediation cell and toxaphene is below the standard. But it is clearly a SDV.	1994	No Further Action	Find the closure report	None				04/28/20			
113	SDV106	New Red Mesa SDV	NN0000125492 Same # as Newman Cell #1	The SDV is located approximately 2.65 miles N of US Hwy 160 on Navajo Rte N-36, and 1 mile W of Navajo Rte N-35. The site has a very loage trench that was apparently used for cattle. There are two SDVs here though!	36.990074	-109.38054	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm toxaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Red Mesa Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
141	SDV134	Ramah W8 SDV		10 miles southeast of chapter 200 ft west of well 8 Vat may be remediated. No vat actually found in the field investigation of 2006. There is a well and corrals at the location of the driving directions. Entered the coordinates accordingly.	34.825647	-108.297345				Needs investigation					04/28/20			
142	SDV135	Red Lake SDV		1/2 mile east of Old Red Lake Store, 300 ft south of hwy 160.	36.323671	-110.932317				Needs investigation								
143	SDV136	Red Rock SDV		100 yds northeast of chapter 25 ft west of well 16T-542.	35.456037	-108.755828				Needs investigation								
144	SDV137	Rio Pescado SDV	NND986669224	10 Miles northwest of the Ranch Chapter. The SDV is located 4 miles S of State Rd-53 E of Ramah, NM on BIA Rd-130.	35.07645	-108.503979	OASystems Final Investigative Report states that Phase 2 was not necessary since the Phase 1 results did not exceed	2002	No Further Action	Find the closure report	None	Route 2, Box 13 Ramah, NM 87321	Ramah Chapter		04/28/20	Restricted		Land Use Restriction on Public Record.
145	SDV138	Rock Point SDV		N of Rock Point community and BIA Rte N-35. W of runway.	36.727829	-109.622116	Removal; Oversight by NSF; BIA, as PRP. Capped with local virgin soil. Closure report; EMI.	2004	No Further Action		2005	PO Box 190 Rock Point, AZ 86545-0190	Rock Point Chapter		01/18/05	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
146	SDV139	Rock Springs East SDV		1.6 crow-miles east of hwy 491 at the junction of hwy 264. approximately 6.3 miles north of Gallup, near the small town of Ya-Ta-Hey, New Mexico. The site is accessed by turning east on to a paved road off of U.S. Highway 491, approximately one mile south of the intersection of U.S. Highway 491 and New Mexico Highway 264. Travel approximately 1.8 miles on this road which quickly becomes unpaved to the site.	35.626501	-108.752928	The 2006 investigation showed toxaphene below the action level.	2005	No Further Action		2006				04/28/20			
147	SDV140	Rock Springs West SDV		2.89 crow-miles west of hwy 491 and 2.0 crow-miles south of hwy 264.	35.605757	-108.828753	The 1996 sampling event showed toxaphene above the action levels but did not say which SDV was sampled.			Pending further assessment.					04/28/20			
148	SDV141	Roof Butte SDV		The coordinates plot to the SDV right in Round Rock. But the well number is right in Chinle, AZ... Round rock has another SDV which has been remediated. See SDV149.	36.512517	-109.472632	A sampling event, undated, comprised of 4 samples was conducted.			Needs investigation					04/28/20			
149	SDV142	Rough Rock SDV		7 NE RR 150 ft south of well 10R-119 which is 7 miles northeast of Rough Rock	36.472824	-109.776011	The 2002 Phase II indicates toxaphene levels below the standard.	2002	No Further Action	Find the closure report	None				04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
150	SDV143	Round Rock SDV			36.529256	-109.449203	The 1996 sampling event shows toxaphene levels below the standard.			Needs investigation					04/28/20			
151	SDV144	Sagebrush SDV		0.7 miles E of BIA Rte N-41 on the road to the Black Mesa/Kayenta Mine. This SDV was not in the original database of dip vats but has been added. It seems to be the same as SDV075 and SDV150.	36.363745	-110.347896	Removal; Oversight by NSF; BIA, as PRP. Capped with local virgin soil. Closure Document not received.	2004	No Further Action		2005	PO Box 441 Piñon, AZ 86510-0441	Forest Lake Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
152	SDV145	Saint Michaels East SDV		Hwy 264/South Creast Rd/Bldg 29A. 2 miles SE of Chapter House, 1/4 mile SE of Notah's residence	35.635339	-109.084687	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/02/94.	1994	No Further Action	Find the closure report	None	PO Box 829 St. Michaels, AZ 86511	St. Michaels Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
153	SDV146	Saint Michaels North SDV		Hwy 264/South Creast Rd/Bldg 29A.	0	0	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/02/94.			Find this SDV		PO Box 829 St. Michaels, AZ 86511	St. Michaels Chapter		01/22/10	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
154	SDV147	Saint Michaels West SDV		Hwy 264/South Creast Rd/Bldg 29A.	0	0	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/02/94.			Find this SDV		PO Box 829 St. Michaels, AZ 86511	St. Michaels Chapter		01/22/10	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
155	SDV148	Salt Seep at Indian Wells #2 SDV			35.231807	-110.086637	The 2002 sampling event indicated toxaphene above the action level.			Needs remediation					04/28/20			

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
156	SDV149	Salt Seep at Standing Rock #2 SDV		Three sets of directions... 1: 2000 ft north of chapter 800 ft southeast of well 15A-27 2: 3 1/2 miles northwest of Dalton Pass Chapter 1000 ft southwest of well 15B-10 3: 4 1/2 miles northwest of chapter 300 ft of well 15B-1	35.862363	-108.390565	the 2002 sampling event shows toxaphene below the action level.	2002	No Further Action	Find the closure report	None				04/28/20			
157	SDV150	San Juan SDV		TheSDV is located 1 mile N of Navajo Rte N-36. The site is situated within a fenced area of the Navajo Nation Storage Yard at San Juan. There are several residential structures located N of the storage yard.	36.736815	-108.496119	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm tosaphene). Closure document pending. Although 39 ppm in two samples and elevated in others.			Pending further assessment.			San Juan Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
158	SDV151	Sanostee SDV		5 miles east and 1 mile north of junction roads #5016, 5010, and 5012. Junction is 3 miles north of Chapter House Did not find this vat in the 2006 field investigations. Same as SDV177.	36.505262	-108.787639	The 2002 sampling event showed toxaphene below the standard. See SDV177.	2002	No Further Action	Find the closure report	None							
159	SDV152	Sanostee BV SDV		12 miles north of chapter or 12 miles west of Chapter House We did not find this vat in the 2006 field investigations. 12 crow miles west of Sanostee is SDV097. It is the same as SDV097	36.421788	-109.102028	See SDV097			Needs investigation								
160	SDV153	Sanostee Hidden Valley SDV		To reach Sanostee Hidden Valley: drive Navajo Rt. 12 N until just past mile marker 61. Turn right on BIA 8080, and go 4.9 miles. A right on this road leads to the valley.	36.271281	-109.003333	The 2003 Phase 2 showed toxaphene well above the action levels.			Needs remediation								
161	SDV154	Sawmill SDV		5 miles S of White Clay, midway between White Clay and Sawmill. 8 miles N of Sawmill on BIA Rte N-72.	36.00835	-109.185017	Bioremediation; Oversight by NSF; BIA, as PRP with OA Systems as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Last sample analyzed 08/15/05.	2004	No Further Action	Find the closure report	None	PO Box 171 Sawmill, AZ 86549-0171	Sawmill Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
162	SDV155	SE of Smith Lake Chapter SDV		The SDV is located in a valley several hundred yards W of State Hwy 271, and S of Mariano Lake Rd.	35.493948	-108.128168	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Smith Lake Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
176	SDV169	Steamboat Springs SDV	AZ983466145	The SDV is located 8 miles north of Chapter House. Except the coordinates are SSE of the chapter house.	35.74555	-109.84555	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	1996	No Further Action	Find the SDV location and then closure report	None				04/28/20			
177	SDV170	Sweetwater #1 Tom Clyded Corral			36.842545	-109.363497	The 2002 sampling event showed toxaphene below the standard.	2002	No Further Action	Find the closure report	None				04/28/20			
178	SDV171	Sweetwater 2 SDV (Emanuel Mission West)		NW of Emmanuel Mission, adjacent to a poorly maintained dirt road.	36.802609	-109.409033	Removal; Oversight by NSF; BIA, as PRP with ASCG as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Closure Documednt not received.	2005	No Further Action	Find the closure report	None	PO Box 106 Teec Nos Pos, AZ 86514-0156	Sweetwater Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineeri ng Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
179	SDV172	Rubble by Sweetwater SDV There were 2 SDVs inSweetwater. Not 3?		A pile of concrete rubble which appears to have been a SDV is located approximately 250 yards NW of the Tom Clyde Corral (SDV #63 - Sweetwater #1).	36.843382	-109.367425	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending. Actually, the 2002 sampling event shows toxaphene above the action level.	2002	No Further Action	Find the closure report	None		Sweetwater Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
180	SDV173	Table Mesa SDV	NND986667780	BIA developing SAP for further assessment. 7 mikles NE of Sanostee. Same as SDV151 and SDV177? Or is it the trench 37 yards to the SE of this one?	36.505068	108.787195	Remediated via removal 7/20/2020		No Further Action			PO Box 219 Sanostee, NM 87461	Sanostee Chapter		01/29/13	Restricted		Land Use Restriction on Public Record.
181	SDV174	Teesto SDV (Near Seba Dalkai)		The SDV is located off State Hwy 87, approximately 5 miles W of Seba Dalkai School off of Navajo Rte N-6820 toward Tolani Lake.	35.49818	-110.514352	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Teesto Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
182	SDV175	Tiger Lookout #2 SDV (Wildcat Butte)		The SDV is located off State Hwy 371 N of the Becenti Chapter House, and E of the hwy. The site is in an open plain with lots vegetation.	35.8763	-108.165269	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Standing Rock Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
183	SDV176	Toadlena SDV	NND986667780	Three miles SW of Toadlena, NM. Also, 7.5 miles W-SW of Two Grey Hills, NM. Pre-dip corral, the dip vat channel, partially dismantled post-dip corral and various posts are visible. There are two houses within 200 feet of this SDV.	36.204377	-108.928367	The 1996 sampling event indicated toxaphene above the action level.	1996		Needs remediation		PO Box 7950 Newcomb, NM 87455	Two Grey Hills/Toadlena Chapters		01/29/13	Restricted	???	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)
7																		
184	SDV177	Tocito Dome SDV			36.505305	-108.78752	The 2002 sampling event showed toxaphene below the standard.	2002	No Further Action	Find the closure report	None				04/28/20			
185	SDV178	Todastonii SDV		5.5 miles W of the intersection of Rte 64 and Rte 160, Approximately 650 ft SE of the windmill.	36.925074	-109.181733	Removal; Oversight by NSF; BIA, as PRP with ASCG as subcontractor; Capped with local virgin soil. Closure Document Pending approval. Last sample analysed 01/13/05.	2005	No Further Action		2006	PO Box 106 Teec Nos Pos, AZ 86514-0156	Teec Nos Pos Chapter		01/05/06	Restricted	Grazing; No housing development	Land Use Restriction on Public Record; Engineering Control = 1 Ac. Plat Size enclosing SDV work area that contains the revegetated soil cap.
186	SDV179	Tohatchi Bioremediation Pit #1, #2, #3, and #4 SDV		W of the road by 0.05 mile; Hwy 491 between Giant and Chevron at Tohatchi, NM.	35.850499	-108.757855	Bioremediation, Federal On Scene Coordinator (FOSC) Robert Mandel provided analytical results. Remaining soil underneath has toxaphene concentrations less than the cleanup goal. No closure document. Last sample analyzed on 12/02/94.	1994	No Further Action	Find the closure report	None	PO Box 1236 Tohatchi, NM 87325	Tohatchi Chapter		01/22/10	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
187	SDV180	Tohatchi-Oak Springs #1 SDV	NND986669646	The SDV is located approximately 0.5 mile E of US Hwy 491 0.8 mile N of mile post 22 on the S side of the community of Tohatchi.	35.844307	-108.748682	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm toxaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Tohatchi Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.
188	SDV181	Tohatchi-Oak Springs #2 SDV		The SDV is 7.6 crow miles NNE of Tohatchi.	35.967672	-108.774366				Needs investigation								
189	SDV182	Tolani Lake (5-1-1) SDV		The SDV is located approximately 50 yards from Navajo Rte N-15.	35.434079	-110.84954	Phase 1 assessment complete. Samples did not exceed screening criteria (40 ppm toxaphene). Closure document pending.	2002	No Further Action	Find the closure report	None		Tolani Lake Chapter		04/28/20	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)	
190	SDV183	Tolani Lake (5-1-2) SDV		The SDV is located NW of Tolani Lake, AZ. To get to the site travel north on BIA Rte 2 from Leupp, AZ, for 13.4 miles. BIA Rte 2 will veer to the NE; but continue N on an unpaved road which gradually bends to the NW. At approximately 10 miles you will cross the Dinnebito Wash. Continue approximately one more mile to the next wash near Tiis Holoni. On foot, follow this wash approximately 0.8 mile to the SW to where it intersects with the Dinnebito Wash and continue down the wash to the SW for another 0.4 miles to the site.	35.552956	-111.068398	Soil samples were collected from around the dip vat area and within the corral-like structure. All Phase I soil sample results did not exceed the screening criteria. Therefore, a Phase II investigation and additional sampling was not conducted.	2005	No Further Action		2006				04/28/20				
191	SDV184	Tolani Lake (5-1-3) SDV		Map and picture in the file. Nothing else.	35.718315	-110.929268				Needs investigation					04/28/20				
192	SDV185	Tony Tsosie SDV Torreon SDV		Approximately 2 miles E of Fort Defiance maybe on Coalmine Rd.	35.727454	-109.027625	The 1996 sampling event showed toxaphene elevated but below the action level.			Needs investigation					04/28/20				
193	SDV186	Torreon SDV		The information in the file is confusing. On one hand someone at the chapter says there are no dip vats associated with the chapter. On the other hand, there is reference to three dip vats in the area within the chapter boundaries. One vat is supposedly covered by housing for the BIA school. It has UTM coordinates and has been entered into the database. A site visit will be necessary. 9 miles S of chapter 200 ft south of well 15B-32 UTM: N 3961720., E 297000	35.228607	-107.24592				Needs investigation 2SDVs 9 miles apart? Is one beneath the new school housing?					04/28/20				
194	SDV187	Tse Zhin Shi Gaah (Black Butte) SDV		Could also be called Sanostee BR. And is likely also called Black Rock Butte in the 2002 sampling event document. The one called Black Butte in the file has similar landscape in the picture' the trees are in the background. Perhaps there were 2 SDVs here.	36.32955	-109.0528	The 2002 sampling event for all aliases of thes SDV indicate toxaphene at or above the action level. However, the 2003 sampling event for Tse Zhini Gaah indicated toxiphaen below the action level.			Pending further investigation					04/28/20				
195	SDV188	Tseyatoh SDV		1 mile east of Chapter House, 100 ft south of well 16K-339.	35.508231	-108.905807	The 1996 sampling event showed toxaphene below the action level.	1994	No Further Action	Find the closure report	None				04/28/20				
196	SDV189	Tuba City SDV		The SDV is located N of Hwy 160 W of Tuba City, approximately 1 mile E of State Rd. 264. The site is in a picnic area setting 0.5 mile off of Hwy 160 E of a 3 acre pond. The pond is within 0.25 mile of the site.	36.129532	-111.210767	Phase 1 assessment complete. Samples did not exceed sdreening criteria (40 ppm tosaphene). Closure document pending.	2002	No Further Action	find the closure report	None		Tuba City Chapter		01/30/13	Restricted	Grazing; No housing development	Land Use Restriction on Public Record.	

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Emposed Institutional Control(s)	
7	SDV205	Yellow Horse SDV			35.936974	-110.025634	The 2002 sampling event showed toxaphene well above the action level. The 2002 Phase II indicates that toxaphene is still above the action level.			Needs remediation					04/28/20				
212																			
213																			
214	NBF010	Arizona Public Service Company-Leupp Substation	NND982399925	Site is approximately 7 miles W of Leupp, AZ situated N of Hwy 15. The substation is adjacent to the El Paso Natural Gas compressor station.	35 08' 09"	111 05' 39"	A 1991 PA was conducted and the alleged PCB spill was not substantiated. The oil was classified as non-PCB containing. The site was deemed No Further Action by USEPA in 1991.		No Further Action	Confirm the NFA		Coconino County, AZ	Arizona Public Service Company	319 Kinsley Ave Winslow, AZ 86047	11/12/91	Restricted, fenced	Industrial-Electric Substation	Build no housing in the vicinity of the facility.	
215	NBF011	Arizona Public Service-Four Corners Power Plant	NND986683530	Site is 5 miles SW of Fruitland, San Juan County, NM. Site can be reached by traveling 7 miles S on County Rd-6675 from Hwy 64 (Formerly Hwy 550).	36 41' 31"	108 27' 41"	A 1922 PA and a 1995 site inspection were done at the electric generating facility. Sample results for total metals and hydrazine indicated no need for further evaluation. USEPA determined No Further Action .		No Further Action	Confirm the NFA		Fruitland, NM	Arizona Public Service Company	PO Box 335 Fruitland, NM 87416	08/21/95	Restricted, fenced	Industrial-Electric Generation	Build no housing in the vicinity of the facility.	
216	NBF014	General Dynamics - Navajo Facility	NND043015387	Plant facility approximately 900 feet E of the intersection of Indian Rte-12 with Indian Rte-54 on Rte-54.	35 44' 43"	109 03' 13"	A circuit board assembly plant. NSF conducted a PA of the site and No Further Action was determined appropriate. USEPA Region 9 concurred.		No Further Action	Confirm the NFA		Fort Defiance, AZ	General Dynamics		07/31/91	Industrial	Industrial	Restricted, fenced, secured building.	
217	NBF015	Kayenta Substation	NND982399933	Substation is located immediately S of the NTUA office in Kayenta, AZ.	36 43' 36"	110 15' 11"	NSF conducted a CERCLA PA in 1991. A No Further Action determination was concurred with by USEPA Region 9.	1991	No Further Action	Confirm the NFA		Kayenta, AZ	NTUA	PO Box 37 Kayenta, AZ 86033	11/12/91	Restricted, fenced	Industrial-Electric Substation	Build no housing in the vicinity of the facility.	
218	NBF017	Navajo Tribal Utility Authority-Black Mesa Substation	NND983467994	Approximately 31.5 miles S of Kayenta, AZ on Indian Service Rd #4.	36 26' 25"	110 23' 35"	In September 1991, a site PA was performed by NSF. USEPA Region 9 concurred with NSF's determination of No Further Action under CERCLA due to no evidence of abandoned hazardous substances of waters at the site.	1991	No Further Action	Confirm the NFA		Navajo County Kayenta, AZ	Navajo Tribal Utility Authority	PO Box 37 Kayenta, AZ 86033	11/12/91	Restricted, fenced	Industrial-Electric Substation	Build no housing in the vicinity of the facility.	

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R
		Site Name	CERCLIS Number	Physical Location/Notes	Latitude °N	Longitude °W	Project Description	Last Year Sampled	NFA?	Action Required	Closure Report Date	Address	Owner/Operator	Physical Address for Chapter Houses; Mailing address for Non Tribal owners	Inventory Listing Updated	Current Use Status	Suitability Type	Specific, Imposed Institutional Control(s)
7																		
219	NBF018	Piñon McGee Trading Post Completed 8-31-2011		205 miles off of N-65 on N-67, Piñon, AZ	3995462.269	569682.429	ESA completed 11/21/07 by ASCG of NM. Fire occurred 5/18/07 then reignited on 5/19/07 before being fully extinguished. Reassessmen required after the fire. USEPA contractor will perform Phase I and II by 8/31/10 for cleanup planning and property redevelopment. Almost certainly	2007	No Further Action	Confirm the NFA		PO Box 1004 Piñon, AZ 86510	Whippoorwill RBDO		01/26/10	Restricted	Redevelopme nt after cleanup	Fenced by RBDO. Land use restriction on Public Record.
220	NBF021	Arizona Public Service Company-Cameron Substation Completed 6-14-2005	NND982400079	The 2 acre site is approximately 3 miles S of Cameron, AZ and 0.75 mile W of Hwy 89.	35° 50' 16"	111° 26' 15"	A 1991 PA was conducted by NSF for an alleged PCB spill. Small spills occurred in the past but each was remediated fwith State oversight. USEPA granted.	1992	No Further Action			Coconino County Cameron, AZ	Arizona Public Service Company	PO Box 83999 Phoenix, AZ 85072-53999	03/23/92	Restricted, fenced	Industrial-Electric Substation	Build no housing in the vicinity of the facility.
221	NBF019	Ganado Community Dump	NND983469883	Approx .5 mi NE Ganado, AZ, 10 acre site west of Rt. 27 & .5 mi N of Hwy 264	36° 12' 17"	109° 33' 45"	Chapter government had it reclaimed.	1/1/2015		Needs Investigation		PO Box 188 Ganado, AZ 86505	Apache County, AZ	Ganado Chaper	04/28/20	Land restriction to industrial use and on public land		Reclaimed by Chapter government
222	NBF020	El Paso Natural Gas Compressor Station	NN0001118306	4.5 mi W of Leupp, AZ. The 118 acre site is one of many stations that keeps natural gas flowing by supplying pressure in pipeline. Cleanup was on unlined impoundment pounds which collected blowdown liquids fr onsite cooling towers	35° 22' 20"	111° 10' 45"	EPNG cleaned up contaminates & disposed of it at certified landfill.	1/1/2015		Needs Investigation		CPO Box 5428 Leupp, AZ 86035	Coconino County, AZ	Leupp Chapter	04/28/20			Cleaned up by responsible party
223	NBF021	Arizona Public Service Company-Cameron Substation	NND982400079	The 2 acre site is approximately 3 miles S of Cameron, AZ and 0.75 mile W of Hwy 89.	35° 50' 16"	111° 26' 15"	A 1991 PA was conducted by NSF for an alleged PCB spill. Small spills occurred in the past but each was remediated fwith State oversight. USEPA granted No Further Action in 1992.	1992	No Further Action			Coconino County Cameron, AZ	Arizona Public Service Company	PO Box 83999 Phoenix, AZ 85072-53999	06/14/05	Restricted, fenced	Industrial-Electric Substation	Build no housing in the vicinity of the facility.