

## Public Record – Summary Information for Regulated Underground Storage Tanks (USTs) Navajo Nation Environmental Protection Agency – Storage Tank Program

**Date Posted to Web: December 30, 2021**


**General Information:** Total Number of UST Facilities: 99  
Total Number of USTs: 268

### Summary of Information for On-site Inspections:

Number of UST Facilities Inspected 26

Inspection Period Dates: October 1, 2020 – September 30, 2021

Percent Compliance (SOC Combined measure): 27%



Note: The COVID-19 Pandemic impacted the program by limiting the number of inspections and follow-up necessary to ensure the facilities are in compliance with the Navajo Nation Storage Tank Act of 2012. Tank, facility, and on-site inspection information is based on financial responsibility, release detection tests, applicable documentation and verification of release prevention equipment. On-site inspections measure compliance with release detection and release prevention requirements with Subtitle I 40 CFR 280.12 and the Navajo Nation Storage Tank Act of 2012.

**Summary Information of Release:**

Number of Confirmed Releases: 1

Release Reporting Period Dates: October 1, 2020 - September 30, 2021

**Summary Information for Release Sources and Causes:**

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Piping	1	4	0	0	0	0	0	0	1	4	0	0	0	0	0	0
Dispenser	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
STP	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unknown	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Totals</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>
# = number, % = percent of total number																

*Note:* Release, sources and cause information is based on release detection/prevention data to verify the necessary tests were performed on the system and verification of equipment operability. Source and cause data were collected using techniques such as reviewing release detection/prevention documentation provided by the facility and by visually inspecting the equipment.

For more information on site-specific UST information on compliance and releases, please submit your written request to:

Navajo Nation Environmental Protection Agency  
 Waste Regulatory Compliance Department  
 Storage Tank Program  
 Post Office Box 3089  
 Window Rock, Arizona 86515